

1 19A NCAC 03D .0540 is proposed for readoption without substantive changes as follows:

2

3 **19A NCAC 03D .0540 REAR VIEW MIRRORS**

4

5 Rear view mirrors shall not be approved if:

6 (1) Loosely mounted.

7 (2) Forward vision of the device is obstructed by mirror assembly.

8 (3) They do not provide a clear view of the highway to the rear.

9 (4) Cracked, broken, have sharp edges or ~~can not~~ cannot be cleaned such that rear vision is not
10 obscured.

11 (5) Very difficult to adjust or they will not maintain a set adjustment.

12 (6) Bus, truck or truck-tractor with a GVWR of 10,001 pounds or more is not equipped with a rear
13 vision mirror on each side. If a vehicle is configured in such a way that the inside mirror is
14 obstructed, a passenger side outside mirror is required.

15 (7) Vehicles manufactured, assembled, or first sold after January 1, 1966 are not equipped with
16 outside rear view mirrors on the driver's side. The passenger's outside rear view mirror is not
17 required equipment on passenger vehicles if an inside rear view mirror is present.

18

19 *History Note:* Authority G.S. 20-2; 20-39; ~~20-183.3(8); 20-183.3(a)(8)~~;
20 *Eff. October 1, ~~1994~~ 1994;*
21 *Readopted Eff. _____, 2021.*